
Digital Luggage Scale

User's Manual for

WS-01: Customized Weighing Scales

Thank you for choosing our luggage scale. This digital luggage scale has the following characteristics:

1. precise weighing,
2. attractive design,
3. easy to carry,
4. durable and more.

It is perfect for travel, family use, shopping, or outdoor activities.

Please read this manual carefully to ensure correct operation of the scale.

SPECIFICATIONS:

1. Equipped with High Precision Strain Gauge Sensor System
2. Maximum Capacity: 40kg
3. Minimum Capacity: 1kg
4. Division: 100g
5. Unit: kg/lb
6. One Button
7. Power: 1 Lithium Battery (CR2032)

Battery Replacement Instructions:

1. Remove battery holder. Place one 3v Lithium Battery (CR2032) in the holder and insert battery holder into scale.
2. LCD displays "888". Within 3 seconds the scale will displays "0.0kg".

Scale Operation:

1. Press the POWER button to turn on scale. The LCD displays '888" at startup. After startup, be sure to hold the scale in a vertical state (within 3seconds) and the LCD display reads "0.0g".
2. Attach the article you want to weigh to the scale, hold the scale, and lift up the article. The scale will display the weight along with an "Hold" in the lower right corner.
3. To reset the scale and weigh another article, remove article from scale, then press and release POWER button. LCD will display "0.0kg".
4. Press POWER button to turn scale off or scale will power off automatically after 60 seconds.

Unit Switching (kg/lb):

1. Press the button to turn on scale.
2. The LCD displays "888" at startup. While LCD displays "888", quickly press button to change the unit to lb or kg.

Tare Function (Using container to weigh item):

1. When you use a container to weigh an article, weigh the container by itself first. LCD displays container weight with "Hold" in lower right corner, continue to lift container, press and release POWER button to reset scale to (0.0).
2. Place an article into container, the scale will display the net weight of the article.

POWER Button Function:

1. Turn unit on/off
2. Reset to zero
3. Activate "TARE"
4. Unit Change when LCD displays 888

Additional Notes:

1. The maximum weight for this scale is 40 KG. If attach more than 40kg to scale, the scale will display "OLD". Attempting to weigh items over 40KG could damage the scale.
2. When the LCD displays "Lo", it means that the battery is low. Please change the battery as soon as possible.
3. To ensure the highest accuracy possible, avoid shaking or rocking while weighing items with the scale.